

Challenge: Damage-free clamping of alloy wheels.

- Plastic clamp covers are missing, or are not installed by technicians, resulting in metal-to-metal contact with wheel.
- Current plastic clamp covers are difficult to use on stiff-sidewall applications.
- Chromed wheels can slip during service while clamped externally.

**Solution: Coats Grip-Max™ Laminated
Clamps****“Maximum Grip, Minimum Risk”****Part No. 85000758 (Set of 4)**

- Plastic protectors are integrated into the clamp so they will not come off.
- Integrated protection eliminates metal to metal contact when clamping externally.
- Updated jaw profile drastically improves ease of use when outside clamping stiff-sidewall tires.
- New Grips offer twice the slip resistance of conventional clamp covers.
- Grips last 30% longer than conventional clamp covers.
- Metal jaws have point contact for traditional inside clamping on steel wheels, and can be replaced without purchasing new clamp bodies.
- 3 Position clamp allows for adjustments covering a wide range of rim sizes.
- Fits all Coats 50X, 70X, and APX Rim-Clamp™ tire changers.

HENNESSY INDUSTRIES, INC.

Manufacturer of Ammco®, Coats® and BADA® Automobile Service Equipment, Tools and Accessories
1601 J.P. Hennessy Drive LaVergne, TN 37086-3565 800-688-6496 or 615-641-7533

Hennessy Canada: 2430 Lucknow Drive, Unite 9, Mississauga, Ontario L5S 1V3 905-672-9440

www.ammcoats.com

Great Customer Value: A customer only has to prevent damaging 3 rims for Grip-Max to fully pay off. If a customer currently replaces clamps every 3 years (at a cost of \$375), clamp covers every 3 months, and the new clamps prevent damage to 2 rims per year (at \$200 each), over a 6 year machine life, the customer will save:

- \$235 in clamp and clamp cover replacement costs.
- \$2,400 in wheel damage.

This equates to a \$2,635 value to the customer, or a \$1,990 savings over the life of the tire changer.



Part No. 85000758 (Set of 4 Clamps, with plungers and 1 extra set of grips)



Part No. 85000768 (Rebuild kit for 4 Clamps: 8 Grips, 8 covers, 4 sets of assembly hardware)



Part No. 8500059408 (Set of 8 replacement Grips)

HENNESSY INDUSTRIES, INC.

Manufacturer of Ammco®, Coats® and BADA® Automobile Service Equipment, Tools and Accessories
1601 J.P. Hennessy Drive LaVergne, TN 37086-3565 800-688-6496 or 615-641-7533

Hennessy Canada: 2430 Lucknow Drive, Unite 9, Mississauga, Ontario L5S 1V3 905-672-9440

www.ammcoats.com